

Date Samples Arrived:	20/08/2018	Customer Name and Address:	AP LANKA (PVT) LTD No 163/26, Nawala Road, Colombo - 05, Sri Lanka
Date Testing Started:	20/08/2018		
Date Testing Completed:	14/09/2018		
Customer Purchase Order No:	Pro-Forma		

Description of Test Samples:	Identity/Serial Numbers:
1 no. Cable Tray	Identified as '1' for testing purposes

Test(s) Performed in the following order unless otherwise specified:	In Accordance With:
Salt Mist Testing	UKAS ASTM B117-16

### Report Summary:


The sample content was subjected to the test detailed above, the particulars and methodology of which are contained in this test report.

On 10/09/2018 the chamber was opened for a period of 1 hour for sample checks and checking of the spray assembly. It was agreed with the customer via email that the test duration would be extended by 1 hour to compensate for this.

Apart from the deviation noted above the test completed correctly.

Some discolouration was noted on 29/08/2018 after 8 days of salt exposure and further discolouration was noted the following day (30/08/2018), particularly around cut-out sections on the cable tray.

The customer requested that the test samples were disposed of on conclusion of the test.

Distribution:	Test Engineer:	Shane Humphrey	 Digitally signed by Shane Humphrey Date: 2018.10.29 10:20:08 Z
1. PARC Ltd File 2. AP LANKA (PVT) LTD			
Sample Disposal:	Approved by:	Sam Wort, Senior Test Engineer	
Sample/s disposed of at the instruction of the customer			